ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	15	T Dasarahalli

Street ID	Street Name	Significant Landmark
W0024, I0254, W0059, W0065, W0028, W0069, W0063, W	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, Om Shakthi Lyt 5th Crs, Om Shakthi Lyt	Dasarahalli

Segment No.	Total Length (m)
15/C-W0024/S012547	596.56

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	25.10	77.513938	13.047117	77.513718	13.047188	1st cross	2nd cross
2	134.13	77.514168	13.047684	77.513752	13.046543	st marys school road	6th cross
3	136.66	77.513881	13.047773	77.513495	13.046597	st marys scl road	6th cross
4	26.85	77.512181	13.046738	77.512417	13.046665	5th crs	6th crs
5	59.28	77.512103	13.047337	77.511982	13.046814	eagle bekary road	kk road
6	105.69	77.512513	13.048278	77.512232	13.047363	nelamaheshwa ramma temple road	eagle bekary road
7	108.85	77.512234	13.048390	77.511958	13.047444	nelamaheshwa ramma temple road	eagle bekary road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements of rcc drain and covering slab maheshwari nagara 6th cross left side roads 7th cross road ward no15 T dasarahalli	7500000	2019-2020

Year	Type of Work	Other Work Type
2019 - 2020	Others	road and drain work

Tender	Work Details	Job No. / Work Code
Not a Tender		015-19-000005

Work Order No.	Work Order Date	Period of Extention
EE/DD/WO/372/2019-20	03/08/2019	

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎಂ.ಪಿ.
ಬೆಂಗಳೂರು-560073

03/08/2019	02/08/2020	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		7493918.00
Phone No.	**E-Mail ID**	
9591836710		

Zone: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0024, I0254, W0059, W0065,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎಂ.ಪಿ.
ಬೆಂಗಳೂರು-560073.

Field Inspection Details

Number of Trees	Any Other Information	Name
1		Archana

Date of Inspection	Remarks
15/07/2020	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Zone: DASARAHALLI **Ward No:** 15 **Ward Name:** T Dasarahalli **Street ID:** W0024, I0254, W0059, W0065,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎಂ.ಪಿ.